	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment
1	BRS	L1	8942	pressure and sensor.ti.	USPA T	2004/07/0 7 11:32	
2	BRS	L2	26805	1 first adj pressure	USPA T	2004/07/0 7 11:33	
3	BRS	L3	13938	2 and second adj pressure	USPA T	2004/07/0 7 11:33	
4	BRS	L4	319	1 and first adj pressure	USPA T	2004/07/0 7 11:33	
5	BRS	L5	319	4 and first adj pressure	USPA T	2004/07/0 7 11:33	
6	BRS	L6	15	5 and hermetic\$3 adj seal	USPA T	2004/07/0 7 13:43	
7	BRS	L7	0	6 and stopper	USPA T	2004/07/0 7 11:34	
8	BRS	L8	0	6 and stop\$3	USPA T	2004/07/0 7 11:34	
9	BRS	L9	75	5 and stop\$3	USPA T	2004/07/0 7 11:34	
10	BRS	L10	0	6 and strain adj dauge	USPA T	2004/07/0 7 11:35	
11	BRS	L11	7	6 and strain adj gauge	USPA T	2004/07/0 7 13:41	
12	BRS	L12	O	5 and diaphragm near3 first adj side near3 pressure and second adj side near3 pressure	USPA T	2004/07/0 7 13:34	
13	BRS	L13	1	5 and diaphragm near first adj side near pressure and second adj side near3 pressure	USPA T; US-P GPUB ; DERW ENT	2004/07/0 7 13:34	
14	BRS	L14	3	5 and diaphragm near first adj side same second adj side	USPA T; US-P GPUB ; DERW ENT	2004/07/0 7 13:35	
15	BRS	L15	8	5 and diaphragm same first adj side same second adj side	USPA T; US-P GPUB; DERW ENT	2004/07/0 7 13:35	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0
11		0
12		0
13		0
14		0
15		0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s
16	BRS	L16	6	5 and diaphragm with first adj side with second adj side	USPA T; US-P GPUB ; DERW ENT	2004/07/0 7 13:35	
17	BRS	L17	0	15 and hermetic\$3 adj seal		2004/07/0 7 13:36	
18	BRS	L18	1	15 and strain adj gauge	i	2004/07/0 7 13:36	
19	IS&R	L19	1	("6062088").PN.	:	2004/07/0 7 13:46	
20	IS&R	L20	0	("19andhermeticadjsea l").PN.	USPA T	2004/07/0 7 13:43	
21	BRS	L21	0	19 and hermetic\$3 adj seal		2004/07/0 7 13:44	
22	IS&R	L22	2	(("5262641") or ("6148673")).PN.	USPA T	2004/07/0 7 13:46	

	Error Definition	Er ro rs
16		0
17		0
18		0
19		0
20		0
21		0
22		0